

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

1 / 12

FIG. 1



2 / 1 2

FIG. 2A




FIG. 2B





FIG. 2C

RF POWER	Si-CH ₂ /Si-CH ₃
560W	0.0245
630W	0.0305
700W	0.0395
770W	0.0487
840W	0.0594


3 / 12

FIG. 3



4 / 12

FIG. 4




5 / 1 2

FIG. 5



		Si-CH ₂ /Si-CH ₃ RATIO
O2 FLOW RATE	→	→
RF POWER	→	→
PRESSURE	→	→
TEMPERATURE	→	→

6 / 12



FIG. 6



7 / 12


FIG. 7A**85. WIRING TRENCH****FIG. 7B**

8 / 1 2



FIG. 7C**FIG. 7D**

9 / 12



FIG. 8



10 / 12

FIG. 9A**FIG. 9B**


11 / 12

FIG. 9C**FIG. 9D**

4045

12 / 12

FIG. 10



BY	PURSUANT TO 37 C.F.R. 1.10	ON	REC'D NO.
EXPIRES	MAIL	FILE	DATE
ORIGINATOR	Fees	RECEIVED	TELEGRAM
ACM 115-040-8030			08-10-1980